CLANVICI

Synclavier³ Hardware and Software Installation and Test

Version 1.01

April 21, 2015

Installation and Setup for the BTB-1	3
Visual Inspection	3
TB-1 Thunderbolt-to-PCI-Express Chassis	4
PCIe-DIO-48 Digital I/O Card	5
BTB-1 Buss Transceiver	6
Twisted-Pair Cable	7
D0-PCI Interface Card	8
Software Installation	9
After Restarting - The Console Application	10
Starting Synclavier ³	11
Real Time Settings	12
Bus Cycle Timing	13
Accessing a SCSI Disk Drive (W0: or W1:)	14
SCSI Data Rate	14
Initial Hardware Verification - The BTB-1 Test Program	15
What is the BTB-1 Test Program	16
Synclavier ³ Control Menu	16
The Logger Test Program	23
Starting The Real Time Software	25

Installation and Setup for the BTB-1

The BTB-1 hardware and the Synclavier³ software form a highly integrated system. Different Synclavier® hardware configurations constructed in different eras require slight differences in the BTB-1 setup.

Once the hardware installation is complete there may be some custom timing settings required for your installation.

Visual Inspection

If you purchased a Thunderbolt Chassis you may wish to

inspect that the Digital I/O card in the Chassis is properly seated and that the two flat cables are firmly attached to the Digital I/O Card. The Thunderbolt Chassis is easily opened with the two thumbscrews.



Thunderbolt Chassis

Detailed assembly instructions for the TB-1 Thunderbolt Chassis are available online at <u>www.synclavier.com</u>.

Visual identification of the different hardware pieces can be aided with our <u>component identification</u> <u>page</u>.

Hot Plug-and-Unplug

Thunderbolt technology provides for the attachment and removal of Thunderbolt devices without powering down or restarting your computer. Synclavier³ supports hot plugand-unplug in certain cases.

You should use the Synclavier³ **Control** menu to **Stop Real Time** before unplugging the Thunderbolt Chassis. Unplugging the chassis while you are using the Sound File Import window to import from a SCSI disk drive is guaranteed to lock up your entire computer.

TB-1 Thunderbolt-to-PCI-Express Chassis

The Thunderbolt Chassis connects to your Thunderbolt-equipped computer using a special Thunderbolt cable. The chassis holds the PCI-Express Digital I/O Card. Earlier Macs have PCI-Express card slots; you do not need the Thunderbolt chassis for those installations.



PCIe-DIO-48 Digital I/O Card

The Digital I/O card plugs into your computer or your Thunderbolt chassis. It connects to the BTB-1 Buss Transceiver using two flat cables.



BTB-1 Buss Transceiver

The BTB-1 Buss Transceiver connects to the Digital I/O card using two flat cables. It connects to your Synclavier® hardware using a special twisted pair cable.



Twisted-Pair Cable

A special twisted-pair cable connects the BTB-1 Buss Transceiver to your Synclavier® hardware. The twisted pairs provide the proper electrical impedance for high-frequency digital signals. An 8-foot twisted-pair cable is recommended, although the BTB-1 is theoretically capable of longer twisted-pair cable runs. Longer runs will provide a slower transfer rate and may be subject to electrical interference.



D0-PCI Interface Card

The D0-PCI Interface Card connects the twisted-pair cable to your Synclavier® hardware. Early D0-PCI cards built for the PCI-1 "Classic" PCI card require a small electrical modification to work with the BTB-1. Newly-produced D0-PCI cards do not require any further modification.



Software Installation

The Synclavier³ software is available for download at www.synclavier.com. After accepting the terms of the License Agreement you will see a folder containing the Synclavier³ application and related components.



Mac OS Versions

Synclavier³ has been tested with Mac OS 10.10 "Yosemite" as well as Mac OS 10.9 "Mavericks".

Both the hardware and software have been <u>designed</u> to allow operation on Mac OS 10.8 "Mountain Lion". however we do not have access to hardware that lets us test that configuration. There may be unexpected problems that show up with the earlier OS.

To use the BTB-1 hardware and MIDI you will have to run the installer which will require a restart. The Synclavier³ can be copied to any convenient location such as you Desktop or your Applications Folder.

The Extras folder includes a copy of InterChangeX that works with the BTB-1. InterChangeX may be useful to you for working with legacy drives and media. InterChangeX is a Carbon application with several screen-drawing problems.

After Restarting - The Console Application

After restarting your computer you should use the Console application (in the Applications/Utilities folder) to verify that the kernel driver was installed and that the Digital I/O card could be found.

If you have a Thunderbolt Chassis, you will see the "Synclavier PCIe PCIDevice: init" message about 5 seconds after you connect your Thunderbolt Chassis.

If you have a PCI-Express Mac Pro, the message may be several pages back in the Console log. To search the console log select the "system log" and cmd-F.

SYSTEM LOG QUERIES All Messages DIAGNOSTIC AND USAGE INFORMATION Diagnostic and Usage Messages User Diagnostic Reports System Diagnostic Reports FILES	11:18:01 AM kernel: IOThunder 11:18:01 AM kernel: IOThunder 11:18:01 AM kernel: IOThunder 11:18:04 AM kernel: [PCI con 11:18:04 AM kernel: [PCI con 11:18:04 AM kernel: Synclavin 11:18:04 AM kernel: Synclavin 11:18:04 AM kernel: Synclavin	erboltSwitch<0xffffff8022556400>(0x3)::list erboltSwitch<0xffffff8022556400>(0x3)::list erboltSwitch<0xffffff8022556400>(0x3)::list enfiguration begin] enfiguration end, bridges 18, devices 17] er PCIe PCIDevice: init					
All Messages DIAGNOSTIC AND USAGE INFORMATION Diagnostic and Usage Messages User Diagnostic Reports System Diagnostic Reports FILES	11:18:01 AM kernel: IOThunde 11:18:01 AM kernel: IOThunde 11:18:04 AM kernel: [PCI co 11:18:04 AM kernel: [PCI co 11:18:04 AM kernel: Synclavi 11:18:04 AM kernel: Synclavi 11:18:04 AM kernel: Synclavi	erboltSwitch<0xffffff8022556400>(0x3)::list erboltSwitch<0xffffff8022556400>(0x3)::list enfiguration begin] enfiguration end, bridges 18, devices 17] er PCIe PCIDevice: init					
DIAGNOSTIC AND USAGE INFORMATION Diagnostic and Usage Messages User Diagnostic Reports System Diagnostic Reports FILES	11:18:01 AM kernel: IOThunde 11:18:04 AM kernel: [PCI co 11:18:04 AM kernel: [PCI co 11:18:04 AM kernel: Synclavi 11:18:04 AM kernel: Synclavi 11:18:04 AM kernel: Synclavi	erboltSwitch<0xffffff8022556400>(0x3)::list enfiguration begin] enfiguration end, bridges 18, devices 17] er PCIe PCIDevice: init					
•••	4000 messages from 4/7/15, 11:58	er PCI Device: start er PCI Device: setPowerState 3 8:55 AM to 4/9/15, 11:18:04 AM					
	sustem log						
SYSTEM LOG QUERIES Image: Comparison of the system log on the system log	✓ Ignore case Apr 19 13:35:49 CJ-MacBook-Pro.local nsurlstoraged[6174]: The read-connection to the DB=/var/root/Library/Caches/ocspd/Cache.db is NOT valid. Unable to determine schema version. Apr 19 13:35:49 CJ-MacBook-Pro.local nsurlstoraged[6174]: realpath() returned NULL for /var/root/Library/Caches/ocspd Apr 19 13:35:49 CJ-MacBook-Pro.local nsurlstoraged[6174]: realpath() returned NULL for /var/root/Library/Caches/ocspd Apr 19 13:35:49 CJ-MacBook-Pro.local nsurlstoraged[6174]: ERROR: unable to determine file-system usage for FS-backed cache at /var/root/Library/Caches/ocspd/fSCachedData. Errno=13 Apr 19 13:35:50 CJ-MacBook-Pro kernel[0]: Synclavier Virtual PCIDevice: init Apr 19 13:35:54 CJ-MacBook-Pro kernel[0]: Synclavier PCI Device: start Apr 19 13:35:54 CJ-MacBook-Pro.local login[43311]: DEAD_PROCESS: 43311						

Starting Synclavier³

When you first start Synclavier³ you will be asked for your license code. Many of the features of Synclavier³ are available if you select the "Demo" option.



Real Time Settings

After you enter your license code you will be presented with the Real Time Settings tab of the Synclavier³ Preferences Window.



o o o o o o o o o o o o o o o o o o o	vier ³	Synclavier ³ Prefe	rences		
Poll for Poll for Poll for Boot to Create Initializ Constru	General Settings r Direct-to-Disk* r D70 MIDI Subsyste r D34 Direct-to-Disk o MONITOR instead External 50 Hz. and the Pedal2 (RTE Pedal uct B-Screen *All Wi rt D100 Superfloppy	Asset Library	sset Library Registration Calibrate Metronome Not Calibrated D24 Poly Generic generic_read_time 10 0 generic_setup_time 5 0 generic_write_time 10 0 generic_end_timing 2 0		
*Requires	rt D115 Communicat	tions Port e Software			
W1: SCSII	D 5 (W0:) Choose			Show In Finder	
O0: Image	File Choose			Show In Finder	

Accessing a SCSI Disk Drive (W0: or W1:)

The Real Time Settings tab includes a control for accessing a SCSI disk drive installed in your Synclavier® hardware. The SCSI disk drive is connected using a D24 SCSI Card.

Synclavier³ can access your real W0: or W1: disk drive using some special software and the BTB-1 Buss Transceiver



SCSI Data Rate

The D24 SCSI card required very specific bus cycle times that are difficult for the BTB-1 to achieve accurately. The result is that access to a real SCSI disk drive is very slow - about 11 seconds per megabyte, or almost 3 hours per gigabyte.

The Sound File Import Window (described elsewhere) can be used to import the entire contents of a W0: or W1: hard drive into a hierarchy of folders and files stored on your computer. Once the import process is completed Synclavier³ can access all your files very quickly.

Initial Hardware Verification - The BTB-1 Test Program

The Synclavier³ application and the associated BTB-1 Buss Transceiver form a complex system. The modern computers are so fast that their I/O instructions have to be slowed down to match the speed of the legacy SynclavierR® hardware. This modulation of the computer I/O bus is accomplished using a combination of timing measurements of the computer hardware conducted during startup, and user settings that can be changed in the Preferences Window.

After you enter your license code (or choose to run in Demo mode) you will be prompted to launch the BTB-1 Test



BTB-1 Test Program

The BTB-1 Test Program itself is stored within the Resources subfolder within the Synclavier³ application bundle. The test program is a simple Unix command-line tool that can be stored anywhere on your computer.

If you are struggling with installation and setup issues you may wish to move a copy of the BTB-1 Test Program to your desktop where it can easily be launched from the Finder.

Program. For most installations it his highly desirable to run the BTB-1 Test Program at this point.

What is the BTB-1 Test Program

The BTB-1 Test Program is a miniature version of the Real Time Software that performs an internal test of the BTB-1 hardware and then uses the BTB-1 to test memory in the polyphonic synthesizer (RAM).

The BTB-1 Test Program is a unix command-line tool and opens in its own window under the Terminal application. Several common error scenarios are shown on the following pages.

Synclavier³ Control Menu

The Control Menu has options for starting and stopping the Real Time Software as well as for launching the test programs. You have to stop the Real Time Software before you can run the tests. Synclavier³ normally starts the Real Time Software automatically; **holding the shift key will prevent starting Real Time**.

Ś	Synclavier ³	File	Edit	Window	Terminal	Control	Help	
						Start R Quit Sy	eal Time nclavier ³	Q
						Force Quit		
						Start MONITOR Start LOGGER Test		
						Close S	Sound File Import Window	
						Launch	BTB1Test	

Synclavier³ Control Menu

Synclavier³ includes a new Control Menu that lets you start and stop the Real Time Software.

It also has options for easily starting the BTB-1 Test Program and the Logger test program. No Thunderbolt, No Digital I/O Card, No BTB-1 Attached



Possible indications include the Thunderbolt chassis turned off, The Digital I/O card unplugged from the PCI-Express slot or problems with the Mac -> Thunderbolt Chassis cable.

Digital I/O Card Installed; Needs Initialization

The Digital I/O Card must be programmed the very first time it is used. This step needs to only be performed once. The card programming is typically performed at Synclavier Digital during system testing. However, if you purchase a replacement Digital I/O Card the programming step will need to be completed.

The programming is done automatically the first time the card is used. However a system restart or Thunderbolt power cycle will be required after the programming is completed.

A message indicating the programming status is presented by the BTB- Test Program.

```
Cameronjones — BTB1Test — 76×20
Start of BTB1Test Program
  Build Date: Oct 27 2017
  Build Time: 13:48:18
  Requires Kernel Memory Version: 4
Looking for PCI/PCIe cards...
   Error: Card could not be initialized
   Code: 130
   Info: Vendor ID 494f Device ID 0c61
New card - programming BAR3
New card - programed OK - Restart required
logout
Saving session...
...copying shared history...
...saving history...truncating history files...
...completed.
Deleting expired sessions...3 completed.
[Process completed]
```

More details about the Digital I/O card programming are available by using the Mac O/S Console application to look at the system log:

•••	system.log
SYSTEM LOG QUERIES	Nov 2 10:33:53 CJ-Mini kernel[0]: Synclavier PCI Device: newUserClient
All Messages	Nov 2 10:33:53 CJ-Mini kernel[0]: Synclavier PCI Device: SetParameter - InitializeHardware (2, 2)
DIAGNOSTIC AND USAGE INFORMATION	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - New AccesIO card detected - programming required Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - Got BAR8 <ptr></ptr>
Diagnostic and Usage Messages	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - LCS_LASORR 0xfffffff1
► User Diagnostic Reports	Nov 2 10:33:53 CJ-Mini kernel(0): InitializePCTHardware - LCS_LAS0BA 0x00000001
▶ System Diagnostic Reports	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIMardware - LCS_LASIRR 0x0000000
FILES	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - LC5_LASIBA 0x00000000 Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - LC5_L8801_0x00000000
system.log	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - LCS_PROT (1) 0x30
► ~/Library/Logs	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIMardware - LCS_PROT (2) 0x12
▶ /Library/Logs	Nov 2 18:33:53 CJ-Mini kernel[0]: Initialize/CHardware - EE_LASIBA 8x00000000
▼/var/log	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIMardware - EE_LBRD1 0x00000040
accountpolicy.log	Nov 2 10:33:53 CJ-Mini kernel(0): InitializePCIHardware - EE_LASIRK 0xTTTTT000 Nov 2 10:33:53 CJ-Mini kernel(0): InitializePCIHardware - EE_LASIBA 0x00000001
accountpolicy.log.0.gz	Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - EE_LBRD1 0x00000240 Nov 2 10:33:53 CJ-Mini kernel[0]: InitializePCIHardware - New AccesIO card detected - programming OK
a	Size: 981 KB A Larler Victor Nov

BTB-1 Connected; Synclavier® Hardware Turned Off

Cameronjones - BTB1Test - 95×17
Last login: Thu Apr 9 11:29:01 on ttys001
CJ-iMac:~ cameronjones\$ /Volumes/CJ\ Movies/XCode\ Build\ Products/10-8/BTB1Test ; exit;
Start of BTB1Test Program (OS X 3/1/2015)
Looking for PCI/PCIe cards...
Vendor ID 494f Device ID 0c61
BTB-1 revision 1 identified
OK: Board pci494f,c61 found; beginning tests...
Testing the Registers on board pci494f,c61...
Registers OK
Error: No poly memory available for test
logout
[Process completed]

BTB-1 Test Program Normal Operation

```
    cameronjones - BTB1Test - BTB1Test - 89×18
    Last login: Thu Apr 9 11:31:10 on ttys001
    CJ-iMac:~ cameronjones$ /Volumes/CJ\ Movies/XCode\ Build\ Products/10-8/BTB1Test ; exit;
    Start of BTB1Test Program (OS X 3/1/2015)
    Looking for PCI/PCIe cards...
    Vendor ID 494f Device ID 0c61
    BTB-1 revision 1 identified
    OK: Board pci494f,c61 found; beginning tests...
    Testing the Registers on board pci494f,c61...
    Registers OK
    OK: Looks like a poly system is available for testing
    Note: Test will run forever. Halt test with ctrl-c
    Time: 0:01:45 Megs: 29 Write MB/Min: 56 Read MB/Min: 16
```

BTB-1 Test Program One Flat Cable Disconnected

```
cameronjones — BTB1Test — 93×21
Last login: Thu Apr 9 11:28:35 on ttys001
CJ-iMac:~ cameronjones$ /Volumes/CJ\ Movies/XCode\ Build\ Products/10-8/BTB1Test ; exit;
Start of BTB1Test Program (OS X 3/1/2015)
Looking for PCI/PCIe cards...
Vendor ID 494f Device ID 0c61
BTB-1 revision 1 identified
OK: Board pci494f,c61 found; beginning tests...
  Testing the Registers on board pci494f,c61...
  Error: PCI - Registers failed
  Code: 0
  Info: Exercise_PCI1_registers failed cable data
  wrote: 0x2710
           Øxffffffff
  read:
  re-read: 0xffff
logout
[Process completed]
```

The Logger Test Program

The Logger Test Program is a comprehensive diagnostic program for the Polyphonic Synthesizer. It exercises all the hardware registers using the BTB-1 Buss Transceiver.

Once your installation passes the Logger test it will likely run the Real Time Software without issue.

For large systems with multiply poly bins the buss cycle times might need to be adjusted. Typically increasing the generic_read_time and generic_write_time to 12 or 14 will slow down the BTB-1 sufficiently to communicate with your Synclavier® hardware.



• • •		Synclavier ^a Terminal		
Error log di	agnostic	- 2015/01/01	Iteration # 5	
Test	Bin #1 Errors		Test	Errors
Serial chain Poly memory addressing Poly Memory Phase accumulator #1 Phase accumulator #2 Sample rate generator A/D controller Amplitude computer #1 Amplitude computer #2 Wave bus Envelope bus Oscillator swap Testing 16 M - Addressin	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Poly memory in bin ith random interfer	D16 timer load D16 vs. D3 timer D4567 Mpy./Divide External memory M64K clocks	0 0 0
<s> - Select test</s>	S		<break> - Exit</break>	

Starting The Real Time Software

The Synclavier® Real Time Software will start automatically when you first close the Synclavier³ Preferences window. You will be prompted to run Logger the first time you start the Real Time Software.

